
HOSE TAPS

FI with Vacuum Breaker Lead Free

Product Specifications







Specifications

Working Temperature 1 $^{\circ}\text{C}$ to $75\,^{\circ}\text{C}$

Max. Pressure Rating 1000kPa

Sizing Chart (MM)

	L	Н	W	TH1	TH2
TH97VBLF	82	81	36	G 3/4"	G 1/2"



Features

Watermark Lead Free Approved

100% Pressure Tested

Blow Proof Spindle

Tested and Certified to AS/NZS 3718

Material Chart

Part	Material		
Body	DR Lead Free Brass		
Bonnet	DR Lead Free Brass		
O Ring	NBR		
Washer	Fibre		
Spindle	DR Lead Free Brass		
Handle	Brass		
Jumper	PA		
Vacuum Breaker	DR Lead Free Brass		
Seal	EPDM		

For more information on Metforge, contact: Austworld 15 Activity Crescent, Molendinar, Queensland 4214 Australia

P. 1300 780 430

F. 1300 780 441

E. info@austworld.com.au

